Diagnosis report of
2021 VOLVO V60 MHEV Momentum Adv

Car details

Color: Blue	CO_2 NEDC Emission: 139 g/km
Fuel type: Petrol	CO_2 WLTP Emission: 154 g/km
Body type: Wagon	Gross Vehicle Weight (GVW): 2240 kg
Number of doors: 5	Engine size: 2.00 l
Number of seats: 5	Cylinders: 4
Mileage: 214 186 km	Power: 120 kw
VIN Code: YV1ZWK6VDM1428810	Fuel consumption: 6.10 l/100km
Gearbox: Automatic	Tire size: 225/50 - 17"
Drive type: Front-Wheel Drive	Longo Stock ID: N819289
Longo Certified	

Car photos



Disclaimer

This report has been generated automatically using the information available in our systems and may not be fully comprehensive or complete. Automated translation technology was used in its preparation, and as a result, minor inaccuracies may occur. If you have any questions or if any part of the report is unclear, please do not hesitate to contact our sales team. They will be happy to assist you.

Diagnosis report of
2021 VOLVO V60 MHEV Momentum Adv

Diagnosis details

Mileage on completion date: 214 186 km

Checked by Longo Shared Service certified diagnostics team: Arnas S., Mindaugas Š., Mindaugas G., Ainis G.

This vehicle has been inspected in accordance with the Longo 150-point checklist, covering the body exterior, interior, and mechanical condition. Based on the inspection performed and the information available at the time of assessment, no indications of involvement in major accidents were identified. Information regarding maintenance history and mandatory roadworthiness inspections is based on available documentation and records from the country of export. Please note that certain general wear and tear issues are considered acceptable and may not be repaired.

Summary of diagnosed issues

During the comprehensive diagnosis conducted by Longo, 5 issues were identified in the vehicle.


Interior	Exterior	Mechanical
1 issues identified	1 issues identified	3 issues identified


Diagnosis process





OBD II diagnosis






Interior

1. Doors: Trims - Condition




Exterior

1. Front: Windscreen Integrity - Free from MOT-Excluding Damage



Mechanical


1. BRAKES: Front Brake Pads (All)



2. BRAKES: Rear Brake Disc (Both)



3. ENGINE MANAGEMENT - FUEL: Turbocharger



Other

1. Brake Test Line Results





2. Diagnostic Photo






3. Air-Conditioning Measurement



4. Add Photo of Front Interior



Preparation and repair report of
2021 VOLVO V60 MHEV Momentum Adv

Summary of work performed in Longo Preparation center

During the preparation process, the following works were performed

Body & Interior

1. Repair Door Panel

Mechanical repairs

1. Front Brake Pads (All)
2. Turbocharger

Cleaning & polishing

1. Body wet wash
2. Full interior deep clean using only hypoallergenic cleaning products
3. Post cleaning body polish

Spare parts used during preparation

1. Brake Pads (LP3300)
2. Gasket Set (EL186520)


Disclaimer
This report has been generated automatically using the information available in our systems and may not be fully comprehensive or complete. Automated translation technology was used in its preparation, and as a result, minor inaccuracies may occur. If you have any questions or if any part of the report is unclear, please do not hesitate to contact our sales team. They will be happy to assist you.

Additional information about

2021 VOLVO V60 MHEV Momentum Adv

Additional pictures






N'FERA PRIMUS
NEXEN


longo
LONGO


longo


longo













MADE IN SWEDEN
VOLVO CAR CORPORATION
e4*2007/46*1315*09
2020
19
723
VOLVO


12°c
09:35
0
km/h
214253
TM 3902.6 km
460 km
TM Ø6.7 ℓ/100 km


12:25
Geležinkelio gatvė
Tinklų gatvė
Tinklų gatvė
3D
Best. inst.
Vooruit
100m
RADIO 1
Verbinden met telefoon...


VOLVO
V60
SUPPLEMENT BIJ DE
GEBRUIKERSHANDLEIDING


Servicebeurt nr. 4
Uitgevoerd
Km 126.621
Datum 18-09-2023
Werkorder nr. 192654
Soort servicebeurt 120.000 Beurt
Autobedrijf v/d Wulp BV
Albert Einsteinstraat 2
3261 LP Oud-Beijerland
Autobedrijf v/d Wulp BV
Albert Einsteinstraat 2
3261 LP Oud-Beijerland
Opmerking
Multi riem.
2x BANDEN
WISSERS VOOR
Servicebeurt nr. 5
Uitgevoerd
Km 162 441
Datum 26-06-2024
Werkorder nr. 196.290
Soort servicebeurt 150.000 Beurt
Reguliere service
Autobedrijf v/d Wulp BV
Albert Einsteinstraat 2
3261 LP Oud-Beijerland
Extra verversings-/vervangingsbeurt olie/filter:
STEMPEL
Opmerking
WISSERS VOOR
Servicebeurt nr. 6
Uitgevoerd
Km 211 455
Datum 24-6-26
Werkorder nr.
Soort servicebeurt
AUTOBEDRIJF ROOCAR
Binnenweg 1
2923 BA Krimpen a/d IJssel
Tel.: 0 1807 - 5 05 44
Fax: 0 1807 - 5 03 03
Opmerking
olie+filter
pollenfilter


12:25
RADIO 1
Verbinden met telefoon...
Auto status
Service
Gebruik Externe Diagnose zodat een Volvo-monteur bij een probleem de autogegevens op afstand kan uitlezen. Neem voor het gebruik van deze dienst contact op met uw erkende Volvo-dealer.
Berichten
Status
TPMS
Service
Tot service
235 dagen
27269 km
20°C
AUTO
25°C




LONGO

Longo 150-point checklist

Every vehicle is carefully examined according to Longo's comprehensive 150-point checklist, ensuring a thorough assessment mechanical condition. Depending on the factors such as condition, mileage, and specifications, additional checks may be includ may be omitted.

Vehicle Identity & History		
Vehicle identification number (VIN) verified	Registration number confirmed	Mileage verified
Year of manufacture confirmed	First registration date confirmed	Service history checked
Last service date and mileage recorded	Next service due date recorded	Previous accident damage check performed
Manufacturer recall status checked	Vehicle documents verified	Number of keys checked
Exterior Condition		
Front bumper inspected	Rear bumper inspected	Bonnet/hood inspected
Roof inspected	Left side panels inspected	Right side panels inspected
All doors inspected	Boot/trunk inspected	Fuel filler cover inspected
Tow bar (if fitted) inspected	Number plate condition confirmed	Paintwork overall checked
Rust or corrosion checked	Gaps between panels checked	Windscreen inspected
Rear window inspected	Side windows inspected	Sunroof/panoramic roof inspected
Interior Condition		
Driver's seat condition checked	Passenger seats checked	Rear seats checked
Seat adjustment mechanisms tested	Seat heating/cooling tested (if fitted)	Seatbelts checked
Carpets inspected	Floor mats inspected	Headlining inspected
Interior trims inspected	Dashboard inspected	Door trims inspected
Armrest inspected	Parcel shelf inspected	Luggage area condition checked
Luggage area carpets checked	Luggage area lighting tested	Spare wheel / repair kit checked
Lights, Mirrors & Glass		
Front headlights tested	High beam tested	Fog lights tested
Daytime running lights tested	Rear lights tested	Brake lights tested
Reverse lights tested	Indicators tested	Number plate lights tested
Side markers/reflex reflectors checked	Interior lights tested	Dashboard warning lights checked
Sun visors inspected	Interior mirror inspected	Exterior mirrors inspected
Electric mirror adjustment tested		
Comfort & Electronics		
Air conditioning tested	Heating system tested	Ventilation system tested
Window heating tested (front/rear)	Power windows tested	Central locking tested
Remote key tested	Child lock tested	Infotainment screen tested
Radio tested	Navigation tested (if fitted)	Bluetooth connection tested
USB/12V sockets tested	Parking sensors tested	Rear view camera tested
Parking assistance systems tested	Cruise control tested	Steering wheel buttons tested
Horn tested	Electronic driver aids checked (lane assist, etc., if fitted)	
Safety Equipment		
Airbags checked via system	Passenger airbag switch checked	ABS warning light checked
ESC/traction control checked	Tyre pressure monitoring system tested	Fire extinguisher/first aid kit present (if supplied)
Engine Bay & Fluids		
Engine starts normally	Engine idles smoothly	Unusual engine noises checked
Engine mounts checked	Drive belts checked	Timing belt/chain condition checked
Battery condition tested	Battery charging tested	Alternator performance tested
Fluid leaks checked	Engine oil level checked	Engine oil quality checked
Coolant level checked	Coolant quality checked	Brake fluid level checked
Brake fluid quality tested	Power steering fluid level checked	Power steering fluid quality checked
Windscreen washer fluid filled	Fuel system checked for leaks	
Braking System		
Front brake discs checked	Rear brake discs checked	Brake pads checked
Brake hoses checked	Brake lines checked	Parking brake tested
Brake pedal response tested	ABS function confirmed	
Steering & Suspension		
Steering wheel alignment checked	Steering response tested	No excessive steering play confirmed
Power steering assistance tested	Front suspension inspected	Rear suspension inspected
Shock absorbers inspected	Springs inspected	Ball joints inspected
Wheel bearings checked		
Wheels & Tyres		
Front tyres tread depth measured	Rear tyres tread depth measured	Tyre wear pattern checked
Tyre sidewalls inspected	Tyre pressures checked	Spare tyre condition checked
Alloy wheels checked for damage	Wheel nuts/bolts secure	Locking wheel nut present
Additional tyre set inspected (if included)		
Exhaust & Fuel System		
Exhaust condition checked	Exhaust leaks checked	Catalytic converter present
Diesel particulate filter present (if fitted)	Fuel tank condition checked	Fuel lines inspected
Fuel filler cap tested		
Road Test & Driving Performance		
Smooth acceleration confirmed	Smooth gear shifting confirmed	Clutch operation tested
Braking performance tested	Driving stability confirmed	